



Soil Map Units - San Joaquin County, 1992

103 Alo-Vaquero complex, 8 to 30% slopes
 113 Calla clay loam, 2 to 8% slopes
 114 Calla-Carbona complex, 8 to 30% slopes
 115 Calla-Carbona complex, 30 to 50% slopes
 116 Calla-Pleito complex, 8 to 30% slopes
 118 Capay clay, 0 to 2% slopes
 119 Capay clay, 2 to 5% slopes
 123 Carbona clay loam, 2 to 8% slopes
 126 Carbona complex, 15 to 50% slopes
 252 Stomar clay loam, 0 to 2% slopes
 253 Stomar clay loam, wet, 0 to 2% slopes
 281 Zacharias clay loam, 0 to 2% slopes

Soil Map Units - Alameda County, 1966

CdB Clear Lake clay, drained, 3 to 7% slopes
 LaC Linne clay loam, 3 to 15% slopes
 LaD Linne clay loam, 15 to 30% slopes
 LaE2 Linne clay loam, 30 to 45% slopes, eroded
 RdA Rincon clay loam, 0 to 3% slopes
 So Sycamore silt loam

- Soil Map Unit Boundary
- Site Area
- Existing Transmission Lines
- - - Proposed Transmission Route
- Roads**
 - Primary road with limited access
 - Primary road
 - Secondary and connecting road
 - Local road
 - Road, major and minor categories unknown
 - Ferry crossing

0.5 0 0.5 Miles

Scale: 1:24000



Sources: *Soil Survey of San Joaquin County* (McElhiney, 1992)
Soil Survey of Alameda County (Welch et al., 1966)



GWF Tracy
 Peaker Project
 Project No. 51-00167032.00

Soil Types Surrounding the
 GWF Tracy Peaker Project

Figure
 8.9-1